



LOSS BULLETIN

EQUIPMENT BREAKDOWN LOSS

Service Station Hot Water Heating Boiler
Overheats Due to Low Water Condition



Risk Solutions

Loss Bulletin
Number 12

**The Boiler Inspection and
Insurance Company of Canada**

www.biico.com

The nature of the incident leading to the boiler's demise was overheating and collapses of the shell plating which occurred as a result of a low-water condition.

This boiler is a small wood fired unit with no information regarding manufacturer, code approvals or when built. There is some suspicion that the unit was made by a local entrepreneur who, it would seem, was unaware of the relevant codes governing the design, construction and operation of boilers. In addition, a code-approved installation would normally require controls to be fitted in order to prevent this type of situation.

Loss Details

Nature of Business: Service station
Type of Equipment: F.B. boiler -
30 psi hot water heating boiler
Age of Equipment: 9 years

Final Loss Settlement Amount:
\$14,690.00



HSB BI&I