



## LOSS BULLETIN

### EQUIPMENT BREAKDOWN LOSS

Two-Colour Printing Press Sustains Damage



#### Risk Solutions

**Loss Bulletin**  
Number 5

**The Boiler Inspection and  
Insurance Company of Canada**

[www.biico.com](http://www.biico.com)

One of the gripper bars which feeds paper or cardboard into the press became jammed. The shaft on this bar is approximately 1/2" diameter and 30" in length and is protected at each end by a metal guard. One of the guards worked loose and became jammed between the fingers of the gripper bar, stalling the machine and bending the gripper bar shaft out of shape.

The business had only one two-colour press. In order to complete the production order in process it was necessary to subcontract to another printer in a neighbouring city.

#### Loss Details

Nature of Business: Printing shop  
Type of Equipment: Printing press  
Age of Equipment: 11 years

Final Loss Settlement Amount:  
Physical damage - \$12,461.99  
Extra expense - \$1,677.02  
Total loss - \$14,139.01



HSB BI&I