



Underground cable damage causes extensive power outage in condo

HSB Canada, part of Munich Re, is a technology-driven company built on a foundation of specialty insurance, engineering, and technology, all working to drive innovation in a modern world, to keep you ahead of risk.

A 4-story condo building experienced a complete electrical outage due to a wiring failure occurring underground in the parking area between the transformer and the building.

A rental generator was required to supply power to residents while repairs were being made. The investigation revealed the underground cable, original to the building, suffered a short, most likely caused by damaged insulation.

Since the original cable was located beneath the concrete parking lot, it was more expedient to re-route the cable through the lawn to the building. As a result, the lawn's sprinkler

system also needed to be dug up and re-installed. It was also determined that a new vault had to be placed underneath and around the transformer.

Loss details

Direct damage: \$95,000 Extra expense: \$49,000

HSB Canada

390 Bay St, Suite 2000 Toronto, ON M5H 2Y2 Tel: (416) 363-5491

hsb.ca

These examples summarize actual and possible losses and coverage. For all terms, conditions and exclusions, consult the actual policy.

© 2023 The Boiler Inspection and Insurance Company of Canada, part of HSB Group. All rights reserved.