



LOSS BULLETIN

EQUIPMENT BREAKDOWN LOSS

Transformer Burn Out Caused Power Interruption at Banquet Hall



Risk Solutions

Loss Bulletin
Number 10

**The Boiler Inspection and
Insurance Company of Canada**

www.biico.com

At 7:00 p.m. on a warm June Saturday evening, the banquet hall was operating at capacity catering two weddings for over 350 guests. The electrical power to the hall was interrupted due to the burn out of the transformer supplying the insured's premises. The two receptions had to be cut short because power could not be restored until 5:00 a.m. Sunday morning.

Our insured lost the income from the abbreviated receptions. They also lost most of the food in cold storage on the premises, which quickly spoiled in the hot, humid conditions.

Loss Details

Nature of Business: Banquet hall
Type of Equipment: Utility owned
1500 KVA transformer
Age of Equipment: 10 years

Final Loss Settlement Amount:
\$20,500.00



HSB BI&I