



## Operator error causes million-dollar loss Equipment breakdown loss

HSB Canada, part of Munich Re, is a technology-driven company built on a foundation of specialty insurance, engineering, and technology, all working to drive innovation in a modern world, to keep you ahead of risk.

During the third shift of the day, the press operator was involved in maintenance of the cylinder assembly. With the machine shut down, the assembly was dismantled and the cutting blade was repaired. The operator then started to reassemble the unit, and fingertightened the assembly, but was called away from this task. When the operator returned, he failed to use the appropriate tool to secure the screws. The unit was restarted, production resumed, and the screws came loose, resulting in the assembly coming in contact with the cylinder. The resulting damage caused a complete shutdown of the press.

The cylinder replacement from Japan took approximately six weeks to obtain and reassemble. The insured was able to use a competitor to complete the order.

### Loss details

**Nature of Business:**

Printer

**Type of Equipment:**

Printing press

**Age of Equipment:**

9 years

**Final Loss Settlement:**

Property damage -  
\$525,000

Business interruption -  
\$550,000

Total - \$1,075,000

**HSB Canada**

390 Bay Street, Suite 2000

Toronto, ON M5H 2Y2

Tel.: (416) 363-5491

[hsb.ca](http://hsb.ca)

These examples summarize actual and possible losses and coverage.

For all terms, conditions and exclusions, consult the actual policy.

© 2020 The Boiler Inspection and Insurance Company of Canada. All rights reserved.



Follow us